

Failure to install the Construction Exit before disturbing the site soils and/or failure to maintain the Construction Exit will result in enforcement action by the City.

HY-LAND SURVEYING, P.A. LAND SURVEYORS

11947 Idaho Avenue N. Champlin, Minnesota 55316 (763) 323-1300

Certificate Surveyors

BENCHMARK: SOUTHEAST PLACE AND **ELEVATION:**

Wire mesh reinforcement (optional) Engineering fabric Metal or wood. SILT FENCE MUST BE post or stake INSTALLED PRIOR TO DISTURBING VEGETATION Fabric anchorage trench backfill with Direction of tamped natural soil runoff flow


Note: Depending upon configuration, attach fabric to wire mesh with hog rings, steel posts with tie wires, or wood posts with staples.

Figure 6.3-2: Typical installation for silt fence

FOUND IRON

913.43

× 910.09



LOT 14, BLOCK 1, CODES HIGHVIEW PARK

The only easements shown are from plats of record of information provided by client.

I hereby certify that this survey was prepared by me or under my direct supervision, and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

Surveyed by us this _____ day of ____ , 20 08

Confirm property may be redeveloped prior to demolition

A demolition permit provides no assurance of permitted future uses

IIMAN IIIMAN Milton E. Hyland, Minn Reg. No. 20262

Property must be restored within sixty (60) days of building demolition/move - utilities abandoned at the property line with a

permit, foundation demolished with a separate permit, debris

must be issued for a new structure within sixty (60) days of the

removed, demolition excavation filled to match adjacent grade and seed or sod placed and maintained at disturbed areas OR a permit

5917 BERNARD PLACE

building demolition/move.